

D.P.BABBAR & ASSOCIATES

STRUCTURAL ENGINEER

E-1/11, Flat No-50, Sector-15, Rohini, Delhi. Ph.- 9313907593

DATED : - 16-09-2022

In accordance with safety requirements under clause 18 of building-byelaws 1983. I Dharampal Structural Engineer License No.- SE-0130 appointed by building occupier / authorized Senior Secondary School Namely Paramount International School at Sector -23, Dwarka, New Delhi run by Delhi. Sanskar Bharti Shiksha Samiti had personally conducted an inspection of the condition and structure at 2:00p.m. dated 16-09-2022 at Paramount International School at Sector -23, Dwarka, New Delhi. The school premises consists of Ground, First, Second and Third Floor and Fourth Floor with terrace. I hereby certify that the structural part of the existing building of Paramount International School at Sector -23, Dwarka, New Delhi have been designed based on calculation and considered safe in accordance with permissible stresses and the slenderness ratio. The building is safe and ready for occupation.



Sign. of Structural Engineer
Er. Dharampal
(MCD Empanelled Structure Engineer)
(Regd. No.- SE/0130)

Er. DHARAMPAL BABBAR
REGN. NO. SE - 0130
D.P. Babbar & Associates
STRUCTURAL CONSULTANTS
E-1/11, Flat No. 50, Sector-15,
Rohini, Delhi. Ph. 9313907593



Manager

Paramount International School
Sector-23, Dwarka, New Delhi-110075



Principal
Paramount International School