



HARYANA

pwd

BUILDINGS &amp; ROADS

O/o Sub Division Engineer,  
Provincial Sub Division No. I  
PWD B&R Br. Sonipat-131001  
Haryana  
E-mail ID:sdepsd1sonapat@gmail.com

To

The Manager,  
Sunrise International School ,  
TDI City Kundli Sector-59 , Sonapat

Memo No. 780 Dated 5/6/2024

**Subject: - Building Safety Certificate in respect Goddess Saraswati Educational Society (Regd.) Kundli at Sonapat.**

Reference: Your Office letter No. GSES/24/201 dated 03.06.2024.

In context of above letter under reference, the school building of Goddess Saraswati Educational Society ( Regd.) Kundli at Sonapat has been inspected by the undersigned along-with J.E In-charge, as per visual inspection of the School building, the general condition of school building seems to be satisfactory and safe as per visual inspection for one year. There is no responsibility of PWD Department regarding structural stability and further necessary action.

DA/ Nil

  
Sub Divisional Engineer,  
Provincial Sub Division No. I,  
PWD B&R, Br., Sonapat

Endst. No.


Dated

A copy forwarded to the Executive Engineer, Provincial Division No. II,  
PWD B&R Br., Sonapat. for kind information and necessary action please.

DA/Nil

Sub Divisional Engineer,  
Provincial Sub Division. No. I,  
PWD B&R, Br. Sonapat

  
Manager,  
Sunrise International School  
TDI City Kundli, Nangal Kalan,  
Distt. Sonapat (Haryana)

  
Principal  
Sunrise International School  
TDI City, Kundli, Sector-59  
Nangal Kalan, Sonapat  
Haryana (meid)-131023