Annexure D

BUILDING SAFETY CERTIFICATE

No. 12 Dated: 17.04.2026

It is certified that the existing building ...GRIZZLY VIDYALAYA..... ...(name of the building or premises) at P.O.: Tilaiya Dam - 825413 Distt. -Koderma (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school 02	Block Academic (1) Block (01)	Block Academic (2) Block (02)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block 04	G+3	G+3				

The building is owned/occupied by....GRIZZLY VIDYALAYA..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Building Constt. Deptt. (Name of Department/ Govt.) on..10.04.2026...(date of inspection) in the presence of Avinash Kumar Seth, Jhumri Telaiya..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from..01.04.26.... for a period of .....one..... years in accordance with rule and subject to compliance of the specific conditions as appended.

1. School building approved map & plan is attached.
2. Certificate of Structural stability from safety consultant is attached.
3. Fire safety NOC from Fire fighting officer Jharkhand Ranchi is attached.
4. The school building is visibly safe & can be used upto 31.03.27 (2026-27)

Issued on 17.04.2026..... at ..Koderma..... by

17.04.2026
सहायक अभियंता
भवन निर्माण प्रमंडल
तिलैया
17.04.26

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for details

Signature with Seal :

Name : AKASH KUMAR SINHA

Designation : Assistant Engineer

Name & Address of Department/ Office: Building Sub-Division, Tilaiya. Koderma

For Grizzly Vidyalaya

Secretary